



LAND USE PROTECTION PROGRAM

MOSQUITO AND VECTOR CONTROL - OFFICIAL INSPECTION REPORT

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME HOOVER RANCH #1				DATE 11/20/2012	SIGNATURE
LOCATION 35999 CARTER ST, YUCAIPA, CA 92399				REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2012
MAILING ADDRESS 35999 CARTER ST, YUCAIPA, CA 92399				<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT	
FA # FA0007347	PR # PR0006300	SR # Not Specified	CO # Not Specified	PE 4001	REHS LeeAnn Drouault
TIME IN 11:31 AM	TIME OUT 1:12 PM	CONTACT Not Captured			PROGRAM IDENTIFIER: CONVENTIONAL/ENVIRONMENTAL/G
					SERVICE: 001 - Inspection - Routine
					RESULT: 05 - Corrective Action / Follow up Required
					ACTION: 03 - Reinspection Required

MOSQUITO AND VECTOR CONTROL - POULTRY RANCH PERMIT ALL

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50

Inspection Violations

No violations cited.

Overall Inspection Comments

Inspection found:

Adult fly population light to moderate on ranch at time of inspection.

Pesticide log recorded use of Ravap in houses 1 - 6 on 11/8 & 11/11 and in houses 7 - 12 on 11/9/12.

Neporex used in all houses on 11/13/12.

Evergreen used as an adulticide twice daily.

No active watering system leaks observed.

Wet manure from prior watering system leaks not treated with lime.

Light to moderate breeding observed.

Wire dropping boards need cleaning.

Follow-up inspection on 11/27/12.

Recommend cleaning wire dropping boards and applying lime to wet manure from prior watering system leaks.